


# Rapid Relube System for Rolls-Royce Engine Fan Blades and Fan Discs

- New Technique for On-Wing and Check & Repair Maintenance Environments
- Achieves An Improved Dry Film Lubricant Coating On The Fan Blade Root and Disc Dovetail

**Distributed Exclusively to North America  
by LKD Aerospace, Inc.**  
Contact **LKD Aerospace**



Part Number	Engine
OMAT 4/71	Trent 700
OMAT 4/72	RB211
OMAT 4/73	Trent 500
OMAT 4/74	Trent 800
OMAT 4/75	V2500

Download Rolls-Royce technical brochure for more information by clicking [here](#).

Note: Repair schemes will be issued in the Aircraft Maintenance Manual (AMM) and Engine Manual (EM) to instruct the new Rapid Re-lubrication technique. Until these schemes are issued in the AMM and EM, Temporary Revisions and Technical Variances are available.

LKD Aerospace, Inc.  
8020 Bracken Place SE, Snoqualmie, WA 98065  
Phone 425-396-0829 Fax: 425-396-1129 Email: OMAT@Lkdaero.com